## SQUAW VALLEY PUBLIC SERVICE DISTRICT



## 2016 WATER AND SEWER SYSTEM REPORT

Prepared April 2017

By

Josh Wilson and

John O'Neal

# Squaw Valley Public Service District Annual Report 2016 Table of Contents

## **Projects**

Title	Page
Capital Improvement Projects and Capital Replacement Projects Summary	1.01
Utilities Report	
Utilities Report	2.01-2.05
Hansen	
This section has been eliminated and will be replaced with VUEWorks in the future.	3.01
Year End Charts and Graphs	
SVPSD Water System Inventory Part I	4.01
SVPSD Water System Inventory Part II	4.02
SVPSD Water Audit	4.03
30 Year Precipitation Trend	4.04
SVPSD Water Production 30 Year Trend	4.05
SVPSD Water Well 1R 3 Year Aquifer Trend	4.06
SVPSD Water Well 2R 3 Year Aquifer Trend	4.07
SVPSD Water Well 5R 3 Year Aquifer Trend	4.08
SVPSD Pump Run Hours	4.09
SVPSD Production Wells Specific Capacity	4.10
SVPWC Water Production 30 Year Trend	4.11
Water Sewer Comparison-Graph	4.12
Water Sewer Comparison-Data	4.13
30 Year Combined Water Production Trend	4.14
Sewer System Inventory	4.15
SVPSD 30 Year Sewer Flow Trend	4.16
SCADA Telemetry	
Annual SCADA reporting is not available at this time.	5.01
Fleet	
Annual Report on District Fleet 2016	6.01-6.02
Annual Report on District Fleet 2017	6.03
Vehicle Manpower and Maintenance Cost Trend	6.04
Operations Fuel Usage 10 Year Trend	6.05

### **EQUIPMENT CAPITAL REPLACMENT PROJECTS**

Budget Year 2018 - 2022

Equipment Type	FY 17	/18	FY 18/19		FY 19	/20	FY 20	/21	FY 21/22		Projec	t Total
Fleet												
Ford F-250					\$	49,900					\$	49,900
Ford F-350									\$	49,200	\$	49,200
Equipment												
Sewer Bypass Trailer and Hose	\$	45,000									\$	45,000
Towable 6" Sewer Bypass Pump							\$	35,000			\$	35,000
Backhoe	\$	150,000									\$	150,000
Small Tools and Equipment												
Air Compressor					\$	21,500					\$	21,500
SCBA Cart	\$	9,500									\$	9,500
Traffic Control Equipment	\$	15,000									\$	15,000
Radios	\$	15,000									\$	15,000
Locators	\$	5,000									\$	5,000
Pipe Freeze Kit/Crimpers	\$	5,000									\$	5,000
Listening Devices					\$	6,000					\$	6,000
Dewatering Pumps	\$	3,000									\$	3,000
New 5.5 kW Portable Generator	\$	4,000									\$	4,000
TOTAL	\$	251,500	\$	-	\$	77,400	\$	35,000	\$	49,200	\$	413,100

#### **WATER CAPITAL PROJECTS**

Budget Year 2018 -2022

CAPITAL IMPROVEMENTS	FY 17	7/18	FY 18/19		FY 1	19/20	FY 2	20/21	FY 21/	22	Proje	ect Total
East Booster Replacement Project (67%	CRP	/33% CIP)					\$	168,300	\$	691,300	\$	859,600
Pressure Zone 1A Project									\$	191,400	\$	191,400
SVPSD/SVMWC Intertie					\$	185,000					\$	185,000
Fire Service Line Detector Check Installa	ation I	Project	\$	50,000	\$	51,400	\$	52,800	\$	54,200	\$	208,400
TOTAL	\$	-	\$	50,000	\$	236,400	\$	221,100	\$	936,900	\$	1,444,400
CAPITAL REPLACEMENTS (FARF's)	FY 1	7/18	FY 18/19		FY 1	19/20	FY 2	20/21	FY 21/	/22	Proje	ect Total
Victor/Hidden Lake 2" Waterline Replace	\$	15,000	\$	102,700							\$	117,700
Zone 3 Booster Pump Station Upgrades	\$	27,600									\$	27,600
West Tank Recoating Project	\$	211,000									\$	211,000
Zone 3 Tank Recoating Project			\$	54,500							\$	54,500
Residential Meter Replacement Project (Includes Irrigation Meter Removal on SFR)			\$	65,400	\$	67,000	\$	68,600	\$	70,300	\$	271,300
Fire Hydrant Replacement Project	\$	31,900	\$	32,800	\$	33,600	\$	34,500	\$	35,500	\$	168,300
TOTAL	\$	285,500	\$	255,400	\$	100,600	\$	103,100	\$	105,800	\$	850,400
GRAND TOTAL	\$	285,500	\$	305,400	\$	337,000	\$	324,200	\$	1,042,700	\$	2,294,800

#### **SEWER CAPITAL PROJECTS**

Budget Year 2018 - 2022

CAPITAL IMPROVEMENTS	FY 1	7/18	FY 1	18/19	FY 1	9/20	FY:	20/21	FY 21/22	2	Pro	ect Total
Truckee River Siphon Project	\$	261,900	\$	1,674,100							\$	1,936,000
Sewer Flow Meter Project			\$	21,100	\$	102,100					\$	123,200
Sewer Cleanout Installation Project (Point of Service Line Cleanouts)					\$	119,600	\$	253,400	\$	256,300	\$	629,300
TOTAL	\$	261,900	\$	1,695,200	\$	221,700	\$	253,400	\$	256,300	\$	2,688,500
	•											
CAPITAL IMPROVEMENTS	FY 1	7/18	FY 1	8/19	FY 1	9/20	FY:	20/21	FY 21/22	2	Pro	ject Total
CAPITAL IMPROVEMENTS Manhole Inspection Project	FY 1	<b>7/18</b> 40,000	FY 1	18/19	FY 1	9/20	FY 2	20/21	FY 21/22	2	Pro \$	ect Total 40,000
	\$	40,000	FY 1	18/19	<b>FY 1</b>	218,000	<b>FY</b> :	339,100	FY 21/22	2	Pro \$	
Manhole Inspection Project	\$	40,000	FY 1	68,200					FY 21/22	37,700	<b>Pro</b> \$ \$ \$	40,000
Manhole Inspection Project Manhole Replacement/Rehabilitation Pro	\$ ogran	40,000 n			\$	218,000		339,100			Pro	40,000 557,100
Manhole Inspection Project Manhole Replacement/Rehabilitation Pro Sewer System CCTV	\$ ogran t Pro	40,000 n	\$		\$ \$ \$	218,000 69,500		339,100	\$	37,700	\$ \$ \$	40,000 557,100 263,400

## **Utilities Report 2016**

## I. Flow Report

- A. Water Production Total = 104.93 MG Comparison: 9.73 MG More Than 2015
- B. Sewer Collection Total = 87.15 MG Comparison: 7.45 MG More Than 2015
- C. Aquifer Level 2016 Maximum Level December 16 2016: 6191.2'
  Minimum Level October 3 2016: 6180.9'

Total Change in Static Water Level 2015: 9.8' Total Change in Static Water Level 2016: 10.3'

- D. Precipitation Total 15/16 Water Year = 64.09" 53- Year average = 51.85" 15/16 Water Year % of the 53- Year average = 123.61%
- E. Flow Report Conclusions: Water production increased 11% over the previous year. Sewer collection increased 9% over the previous year.
- \* The maximum level represents a rough average of the highest levels measured in the aquifer during spring melt period.
- \*\* The lowest level recorded in the aquifer was 6,174.0 feet above mean sea level on October 12, 2001. This level is not necessarily indicative of the total capacity of the aquifer.
- \*\*\* Creek bed elevation (per Kenneth Loy, West Yost Associates) near Well 2r is 6,186.9 feet.
- \*\*\*\* The season total for Precipitation is calculated from October 2015 through September 2016.
- \*\*\*\* The true average could be higher or lower than the reported value due to the uncertainty of the Old Fire Station precipitation measurement during the period 1994 to 2004.
- \*\*\*\*\* The production number is different than scada reports due to time of day reading issues.

### II. Leaks, Repairs, and Maintenance

#### A. Water

- 1. New meters installed: 5
- 2. Water meters replaced or rebuilt: 4
- 3. Water meter upgrades: 0
- 4. Customer service water meters turned on or off: 8
- 5. Routine leak/high usage detection notification: 160
- 6. Customer requested leak detection services performed: 21
- 7. No water responses: 2
- 8. Fire hydrants flushed: 139
- 9. Blow-offs flushed: 14
- 10. Valves exercised: 13
- 11. Repair/Replace service line: 0
- 12. Repair leak on water main: 0
- 13. Backflow devices tested: 505
- 14. Test District backflows: 8
- 15. Quarterly vault inspections on Well 1R and Well 3: 8
- 16. Water tank inspections: 8
- 17. Water quality complaints serviced: 1
- 18. Tested commercial meters: 28
- 19. Replaced Air/Vac breakers: 0
- 20. Water samples collected:

Bacteriological: 32

Nitrate: 5 Asbestos: 1 Manganese: 1

#### B. Sewer

- 1. Sanitary sewer overflows: 0
- 2. Main line repairs: 0
- 3. Service line repairs: 0
- 4. Sewer cleanout repair: 0
- 5. Manhole repairs: 6
- 6. Manhole grouting: 5
- 7. Cleaning:

Spring and fall cleaning of high priority lines

Main sewer lines cleaned: 330

8. Inspections:

Sewer code related inspections: 22

Pre-remodel inspections: 15

Finals inspections: 17 USA locations: 94 FOG Inspections: 28 Toilet Inspections: 13

#### III. Building and Grounds Maintenance and Repair

- A. 305 Squaw Valley Road Fire Department and Administration
  - 1. Continued monthly service and maintenance of facility and equipment.

#### B. 1810 Squaw Valley Road District Equipment Garage

1. Continued monthly service and maintenance of facility and equipment.

#### IV. Vehicles and Equipment

#### A. Vehicles

- 1. All vehicles received an annual service, with the exception of the Ford Interceptor and Ford F-150 which received biannual services.
- 2. Installed new decals on all vehicles.

#### B. Equipment

- 1. All small equipment received an annual service.
- 2. Installed new decals on all equipment.

#### V. Administrative

- A. Hanson data input.
- B. VUEWorks migration from Hanson.

#### VI. Operation & Maintenance Projects

- A. Completed Well 5R project, piping and valves.
- B. West Tank road repair.
- C. Leak detection on district meters and fire hydrants.
- D. SCADA upgrade project phase II completed and 2016-2017 SCADA upgrade substantially completed.
- E. Horizontal Well brush, bushes and tree clearing.
- F. Gate valve box repairs.
- G. Continued Operations and Maintenance of SV Mutual Water Company.
- H. Sewer System I/I inspection.
- I. Cleaned sewers mains in front of the 4<sup>th</sup> phase of the CCTV Project.
- J. Tested commercial meters for accuracy.
- K. Manhole Repairs.
- L. Spring and Fall Flushing.
- M. Annual Sewer Cleaning.
- N. High Priority Cleaning.

#### VII. Summary

This season the District was able to make many repairs to damaged assets. We completed Well 5R project, a much needed face lift with new valves, meter, spool and coated floor. The District continued a contract to operate and maintain the Squaw Valley Mutual Water Company. Training continued this year keeping the district crew as knowledgeable and up to date as possible so that we may provide the best available service to our customers.

## VIII. Safety Training Slip Trips and Falls, SDRMA Safety Booklet 1/8/2016 Josh, Brandon, Jason, Jesse, John 3/11/2016 Water Industry Blood Borne Pathogens, SDRMA Online Devin, Jason, Schel, John Driving Safety, SDRMA Online 4/15/2016 Jason, Schel, John Hand Washing, SDRMA Safety Booklet 5/6/2016 Jesse, Josh, Brandon, John, Jason, Devin, Schel Sexual Harassment Awareness, SDRMA Online 5/19/2016 Devin Water Industry Lock-Out/Tag-Out, SDRMA Online 5/20/2016 Devin, Jason, Schel, John Strains and Sprains, SDRMA Safety Booklet 6/10/2016 Jason, Josh, Brandon, Schel, John, Devin 6/24/2016 Incident Reporting, SDRMA Safety Booklet John, Josh, Devin, Schel Water Industry Working in Extreme Temperatures, SDRMA Online 7/15/2016 Devin, Jason, Schel, Josh, John 8/18/2016 Office Safety, SDRMA Safety Booklet John, Jason, Devin, Schel, Brandon 10/14/2016 Fire Extinguishers, SDRMA Safety Booklet Shel, Josh, Devin, Jason Holiday Stress, SDRMA Safety Booklet 11/18/2016 Devin, John, Schel, Jason, Brandon, Josh

### IX. **Occupational Training** 3/30/2016 Confined Space Certification, TSD Schel, Josh 4/8/2016 Revised IIPP and Code of Safe Practices, Crew Room 305 Brandon, Schel, Jason, Devin, Josh, John 4/20/2016 UTA Locator Class, Sacramento Brandon, John 4/28/2016 TCR Implementation Workshop, Sacramento Brandon, Josh Certificate of Analysis, Crew Room 305 6/22/2016 Josh, Schel, Jason, Devin 7/18/2016 Vac-Con Operation/Maintenance/Trouble Shooting, Sacramento Jason, Josh, Schel SSMP Element 6 SSO Emergency Response Plan, Crew Room 305 10/7/2016 Devin, Jason, Josh, John, Brandon 12/8/2016 Workplace Safety and OSHA Compliance, Reno Josh, Brandon

## Water System Inventory – 2016

#### Part I

- 1. Water Well #1R 389 GPM averaged. \*
- 2. Water Well #2R 323 GPM averaged. \*, \*\*
- 3. Water Well #3 120 GPM averaged. \*
- 4. Water Well #4 (Not in Service)
- 5. Water Well #5R 400 GPM averaged. \*
- 6. Horizontal Well 70 GPM averaged. \*, \*\*\*

#### 2016 Total average flow - 1,302 GPM \*\*\*\*

- 7. West Tank 1,150,000 Gallon Water Tank
- 8. East Tank 500,000 Gallon Water Tank
- 9. Zone 3 Tank 135,000 Gallon Water Tank

#### <u>Total Storage – 1,785,000 Gallons</u>

- 10. 2 Booster Pumping Stations
- 11. 800 Water Meters connected per Billing
- 12. 129 Fire Hydrants
- 13. 31 Air Release Valves
- 14. 505 Backflow Prevention Devices
- 15. 404 Gate Valves
- 16. 17 Butterfly Valves
- 17. 22 Blow Off Assemblies
- 18. 5 Control Valves (Granite Chief, East Booster, Zone 3 Booster, Hz Well)
- 19. 3 Transducer Stations (West Tank, East Tank, and Zone Three Tank)
- 20. 7 Remote Terminal Units (RTU), SCADA Telemetry System

## **Water System Inventory – 2016**

#### Part II

- 21. 12,761 Feet 12" Water Distribution Main
- 22. 10,752 Feet 10" Water Distribution Main
- 23. 29,461Feet 8" Water Distribution Main
- 24. 21,145 Feet 6" Water Distribution Main
- 25. 696 Feet 4" Water Distribution Main
- 26. 990 Feet 2" Water Distribution Main
- 27. 439 Feet 6" Water Service Line
- 28. 240 Feet 4" Water Service Line
- 29. 2,638 Feet 2" Water Service Line
- 30. 254 Feet 1.25" Water Service Line
- 31. 39 Feet 1.5" Water Service Line
- 32. 3,003 Feet 1" Water Service Line
- 33. 128 Feet <sup>3</sup>/<sub>4</sub>" Water Service Line

Total Water Main = 75,805 Feet = 14.357 Miles Total Water Services = 6,741 Feet = 1.276 Miles Combined Total = 82,546 Feet = 15.677 Miles

<sup>\*</sup> GPM averaged from the time wells were on and running.

<sup>\*\*</sup> Well 2r GPM is affected by seasonal aquifer level changes. During low aquiver level years the well GPM is reduced to prevent pumping below the well screens. Flow averages in 2016 ranged from 293 GPM to 347 GPM.

<sup>\*\*\*</sup> Horizontal Well GPM is affected by gravity flow and changes from one year to the next. Longer periods of operation will lower the GPM average.


<sup>\*\*\*\* 2016</sup> total average flow does not indication total capacity. This total is the combined GPM flows from all the wells as they were operated in 2016.


## Squaw Valley Public Service District - Year End Water Audit Report


			Report Date:	March 24, 2017	Performed By:	John O'Neal
	Year:	2016				
			December 31, 2015			
		End Audit Period:	January 4, 2017			
		T . I.M . I.O		· · · · · · · · · · · · · · · · · · ·		00 400 500
		Total Metered Consu	mption for audit period	specified (including r	nydrant meters): [	89,433,598
			Additional Consumption	on - Unmotored		
			Fire Department Use:	101,500		
			Hydrant Flushing:	<u>849,888</u>		
			Blow-Off Flushing:	33,538		
			Sewer Cleaning:	<u>62,000</u>		
			Street Cleaning:	02,000		
			Well Flushing:			
			Tank Overflows:			
		Unread Me	eter Estimated Reads:	50,000		
		Omoda wi	Other:	00,000		
		Total Unmetere	d Consumption (for au	dit period specified):	1,096,926	
			1		, , -	
			Estimated Unknown Lo	oss - Unmetered		
			Known Theft:			
		Know	n Illegal Connections:			
	Tota	al Estimated leaks tha	t have been repaired:	<u>150,800</u>		
		Total Estima	ited Unmetered (for au	dit period specified):	150,800	
			Total	Production for audit	ariad apacified.	106 150 710
			TOTAL	Production for addit p	benoa specinea. [	100,132,713
		Total	Metered/Unmetered Co	onsumption for audit a	period specified:	90.681.324
						, , -
		Total '	Water Loss (Production	on - Consumption):	15,471,389	
				Loss Percentage:	14.6%	***
_						
		•	are different than the a	<u>'</u>		me
			e meter reading schedu			
		41,684 gallons of water	er from 2015. The loss	percentage was brou	gnt down 1.7%	
from 20	)15.					


<sup>\*</sup> Note - All Production & Consumption Totals In U.S. Gallons \*


<sup>\*\*\*</sup> Note - Total Water Loss Percentage includes theft, Illegal Connections or Leaks that have been repaired











	Pump Run Hours												
	Well #1R	Well #2R	Well #3	Well #5R Motor	Well #5R Pump	<b>East Boost</b>	Zone-3 #1	Zone-3 #2					
Year Installed	2005	2011	2014	1999	2015	2015	1990	1990					
1990							30	30					
1991							98	66					
1992							112	84					
1993							120	99					
1994							136	146					
1995							223	160					
1996							363	145					
1997							538	338					
1998							438	352					
1999							612	264					
2000							527	640					
2001							631	573					
2002							493	514					
2003							509	503					
2004							541	550					
2005	209						486	473					
2006	1,868						455	468					
2007	1,796						438	467					
2008	1,552						477	460					
2009	1,552						533	388					
2010	1,637			172			381	365					
2011	1,866	687		1,983			353	344					
2012	1,570	1,569		1,681			513	482					
2013	1,927	1,923		1,884			417	408					
2014	933	1,985	642	1,991			391	393					
2015	1,375	1,399	1,358	985	150	348	312	325					
2016	1,341	1,326	1,317	1286	1,286	1,347	415	409					
Total Hours	17,626	8,889	3,317	9,982	1,436	1,695	10,542	9,446					

#### Notes

Annual and total hours in this spreadsheet are restarted from the time of replacement or rebuild of equipment.

Well 1R - the pump and motor was replaced in 2005 after 24,756 hours in service.

Well 2R - the pump and motor was replaced in 2011 after 42,644 hours in service.

Well 3 - the motor was replaced in 2008 after 12,116 hours in service.


Well 3 - the motor was replaced in 2014 after 5,787 hours in service.


Well 3 - the pump was replaced in 2014 after 17,903 hours in service.


Well 5R - the motor was rebuilt in 2010 after 20,246 hours in service.

Well 5R - the pump was replaced in 2015 after 28,792 hours in service.

East Booster - the pump and motor was replaced in 2015 after 18,822 hours in service.








	Water and Sewer Production 2016											
	WATER	WATER	WATER	SEWER								
	SVPSD	MUTUAL	TOTAL	TOTAL								
JAN	8.07	1.36	9.43	9.98								
FEB	7.48	1.42	8.90	10.29								
MAR	7.28	2.14	9.42	11.84								
APR	5.85	1.24	7.09	7.16								
MAY	6.44	1.73	8.17	5.10								
JUNE	11.10	3.38	14.48	4.98								
JULY	15.49	4.68	20.17	6.71								
AUG	13.76	4.35	18.11	5.89								
SEPT	11.12	3.65	14.77	4.91								
OCT	6.79	2.12	8.91	5.16								
NOV	4.24	1.32	5.56	4.67								
DEC	7.31	1.66	8.97	10.46								
	104.93	29.07	134.00	87.15	Million Gallons							
		ater informat										
	Sewer information comes from SCADA											

## 30 Year SVPSD and SVMWC Combined Water Production Trend




Information comes from from well logs

#### **SEWER SYSTEM INVENTORY – 2016**

- 1. 435 Sanitary Manhole
- 2. 2 Siphons (6"-10")
- 3. 4 Sewer Flow Meter
  - Mag Meter, Painted Rock Siphon T-45A District owned
  - Mag Meter, Mountain Run Ski Corp owned
  - Mag Meter, HWY 89 T-TSA owned
  - Flume Meter, HWY 89 T-TSA owned (Not in Service)
- 4. 172 Feet 16" Sewer Main
- 5. 11,791 Feet 15" Sewer Main
- 6. 2,689 Feet 12" Sewer Main
- 7. 9,245 Feet 10" Sewer Main
- 8. 17,957 Feet 8" Sewer Main
- 9. 51,985 Feet 6" Sewer Main
- 10. 6,687 Feet 4" Sewer Main
- 11. 44,152 Feet 4" Sewer Lateral
- 12. 1116 Sewer Connections per Billing
- 13. 2 Remote Terminal Units (RTU)

Total Sewer Main = 100,526 Feet = 19.039 Miles Total Sewer Laterals = 44,152 Feet = 8.362 Miles Combined Totals = 144,678 Feet = 27.401 Miles



#### 2016 Annual Report on District Fleet

It is management's goal at the Squaw Valley Public Service District to have a robust emergency ready fleet capable of supporting a high level of maintenance and repair of the water and sewer infrastructure in Squaw Valley. Annual review of the fleet is integral to supporting this goal.

The overall age of the District fleet has increased slightly and is now 12.9 years. There is one vehicle being considered for replacement in 2017. The 1994 JCB Backhoe is passing the 23 year mark and will need new front tires and valve body repairs estimated at \$6,000. The unit is underpowered for manhole work and undersized for pipeline replacement work.

The attached spreadsheet summarizes District vehicle and equipment by year, model, mileage, age, replacement schedule, and remaining service life. Additionally there are maintenance and cost projections for the coming budget year. Maintenance costs to date are on track with 2016 budget projections.

As management looks forward to the next few years of fleet management there are vehicles and equipment that should be analyzed and considered for replacement as follows:

**1994 JCB Backhoe:** The backhoe is 23 years old with 3,185 hours. Although the equipment was envisioned to last up to 25 years, We are projecting some potentially serious problems if replacement is delayed. There is a leak in the valve body that was estimated by both JCB and John Deere to cost about \$6,000 to repair. There have been failures of the front spindles, which are likely to reoccur and there is a problem developing with the rear drive axel, which is loose and making noise. The JCB will need a new set of front tires this year.

The JCB dealer in Reno closed their doors several years ago and their mobile mechanic now comes from Sacramento making even minor repairs problematic; obsolescence due to age means parts must come from overseas or Canada. The JCB is a lightweight and low power alternative that cost far less than comparable equipment when purchased. Research shows present value around \$15,000 to \$18,000 retail. However, it is a tier zero engine that cannot be re-sold in California.

The Utility Department would benefit from a heavier and slightly more powerful replacement such as a John Deere 410 HL. We recommend replacement of this vehicle for the 2017/2018 budget cycle. The cost of replacement is estimated at \$150,000.

**1999 Ford F250 Utility Truck:** This vehicle is 18 years old with 57,581 miles. This vehicle is in good condition with no known problems. We recommend the service be extended and replacement scheduled in 2019 or 2020.

**Vac-Con Rear Engine Retrofit:** Retrofit of the Vac-Con rear engine with a catalytic converter is required under California emission regulations by December 2018. The District will be required to begin reporting fleet emissions in 2018 and will not make the required fleet average unless this is accomplished. We are in the process of finding out who is capable of installing this and how much it will cost the district.


**Replacement Timeline:** Attached is a 5 year timeline for vehicle and equipment replacement with estimated costs. In the past 5 years the fleet average has climbed to 12.9 years and the budget is averaging \$12,987 annually. Over the same decade maintenance manpower has moved from \$10,422 annual average to \$16,098 annual average. As our Fleet is aging our costs for maintenance and manpower are rising.

**Recommendation:** It is recommended that the JCB Backhoe be replaced in budget cycle 2017/2018. This will give us a more reliable and capable piece of equipment that we can use in the district. If replaced by January 1<sup>st</sup> 2018, we also will be credited by the Placer County Air Pollution Control District and will extend compliance for the rest of our vehicles through 2022.

# Annual Report on District Fleet

2017												
Vehicle/Equipment	Mileage	Age	Replacement	Service	Annual	Maintenance	2016	Maintenance	2017			
	Hours		Schedule	Life	Use	Performed	2017	Due	2018			
2008 Ford 1 Ton 4x4 Flat	32,452	9	15	6	2,490	Annual Service	\$105	Annual Service	\$125			
						Starter/Battery	\$270	Fuel/Air filters	\$30			
1999 Ford Utility 4x4	57,581	18	15	-3	3,181	Annual Service	\$105	Annual Service	\$125			
						Battery	\$151	Fuel/Air filters, Spark plugs	\$70			
2014 Dodge Ram 4x4	28,960	3	15	12	4,480	Annual Service	\$105	Annual Service	\$125			
						Seasonal Tires Changed	\$60	Seasonal Tires Changed	\$60			
1997 Ford Explorer	121,574	20	15	-5	1,960	Annual Service	\$105	Annual Service	\$125			
								Fuel/Air Filters	\$20			
2014 F-150 4x4	42,180	3	15	12	16,137	2x Annual Service	\$210	2x Annual Service	\$250			
						Seasonal Tires Changed	\$60	Seasonal Tires Changed/Filters	\$100			
2008 F-750 Dump Truck	7,613	9	30	21	466	Annual Service	\$105	Annual Service	\$125			
								Fuel/Trans./Air Filters, Coolant	\$190			
1998 JD 444H Loader	3,374	19	30	11	48	Annual Service	\$105	Annual Service	\$125			
						Block Heater/Emissions Sticker	\$150	Hydro fluid/filter,fuel filter,air filter	\$720			
1994 JCB Backhoe	3,185	23	30	7	47	Annual Service	\$105	Annual Service	\$125			
								Front Tire Replacement	\$2,000			
1998 JD Air Compressor	364	19	20	1	6	Annual Service	\$105	Annual Service	\$125			
								Fuel Filter	\$25			
2007 New Holland	392	10	30	20	9	Annual Service	\$105	Annual Service	\$125			
Westa Sno Blower			20	10		Block Heater	\$90	Hydro filters, Air filters, coolant filters				
						Shoot Motor, Clutch Repair	\$628	Fuel filters	\$300			
2009 Vac-Con Hydro-Vac		8	30	22	531	Annual Service	\$105	Annual Service	\$150			
Power Take Off (PTO)	239	8	30	22	9			Hydro/Air/Fuel Filters	\$850			
2009 Duetz Rear Engine	586.2	8	30	22	78	Annual Service	\$105	Annual Service	\$150			
								Fuel/Air Filters	\$250			
2016 Ford Interceptor	3461	1	15	14	3,307	2x Annual Service	\$210	2x Annual Service	\$250			
								Winter Tires	\$1,200			
6" Trash Pump (2000)	42.2	17	30	13	2	Annual Service	\$105	Annual Service	\$125			
								Filters	\$35			
2010 Prowler Easement	41.3	7	20	13	5	Annual Service	\$105	Annual Service	\$125			
Well House Generator	217.9	24	40	13	8	Annual Service	\$105	Annual Service	\$125			
(1993)								Coolant, Fuel Filters	\$80			
1810 Generator (1991)	778	26	40	14	13	Annual Service	\$105	Annual Service	\$125			
305 Generator (2004)	145	13	40	27	7	Annual Service	\$105	Annual Service, Fuel/Air Filters	\$270			
Equipment/Old Vehicles							\$100	Equipment	\$600			
Miscellaneous Shop Supp						Rags,Cleaning supp. Ect.	\$106	Rags, Cleaning Supp. Ect.	\$800			
Total	Fleet Ave.	12.9					\$3,715		\$10,025			

## Vehicle Manpower and Maintenance Costs



## SVPSD Operation Department 10 Year Fuel Useage Trend

